

# CIRCULAR

## DBS PORT STATE CONTROL INSPECTION REGIME 2013

Dromon Bureau of Shipping presents the most frequent detainable deficiencies imposed on board DBS vessel as well as the new EU Directive on PSC requirements.

DBS PSC-division is publishing the sixth PSC inspection regime on March 14, 2014. The publication present the most frequent detainable deficiencies imposed on board Dromon fleet during 2013 as well as compare the PSC inspection results for the past three years.

Additionally, the publication includes the Concentrated Inspection Campaigns (CICs) will be carried out by Paris MoU in co-operation with Tokyo MoU in 2015 and 2016. Moreover, DBS PSC performed a CIC on MLC, 2006 Implementation and present the most common recommendations imposed on Dromon fleet.

Finally, the publication includes the procedure how the vessels are targeted for an inspection by Paris MoU. Companies shall take into serious consideration this new EU Directive on Port State Control requirement as the performance of the Company may target a vessel and vice versa.

**NOTICE TO**  
SHIP OWNERS / MANAGERS / OPERATORS  
DBS STATIONS / AUDITORS

**CONTACT US**



### REVISED DBS PSC CHECKLIST

The publication includes revised DBS PSC checklist that takes into consideration the requirements of the ILO Maritime Labour Convention (MLC), 2006 coming into force on August 20, 2013. Ship Managers / Owners should forward the revised checklist on board their ship.

The full DBS publication can be found attached to this Circular.

**For Surveyor's use only:**

I confirm that I have received, read & understood this Circular C14002

Name: \_\_\_\_\_

ID No: \_\_\_\_\_

Signature: \_\_\_\_\_



**DROMON BUREAU OF SHIPPING**